

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18<sup>TH</sup> STREET - SUITE 500
DENVER, CO 80202-2466
http://www.epa.gov/region08

Ref: 8EPR-SR

March 27, 2000

Ms. Margo Blu 1460 Cherokee Street City and County Building Room 39 Denver, CO 80204

RE: Soil Sampling at Northeast Montessori Child Care Center

## Dear Ms. Blu:

I am pleased to tell you that EPA has completed the testing of the soil samples collected from the Northeast Montessori Child Care Center at 3503 Marion Street, Denver. The soil was tested for arsenic and lead as part of the Vasquez Boulevard/Interstate 70 Superfund Site investigation. We analyzed 30 samples from the property. The results are reported in parts of arsenic and lead per million parts of soil. Your results are shown in the two tables attached to this letter. A map which shows the location of the samples is also attached.

EPA looks at these results to determine whether a cleanup of the soil in the child care center property is needed. If the results indicate levels greater than 400 arsenic and/or 2,000 lead, the soil will need to be cleaned up.

Your results show that we did not detect arsenic in 18 out of 30 samples. Our limit of detection is 11 parts per million. Only 12 samples contained detectable amounts of arsenic and only slightly above the detection limit (maximum value was 19). The level of lead is not of concern. Clean up action is <u>not required</u> at the child care center property. This means that the property is not considered to be part of the Vasquez Boulevard. I-70 Superfund Site.

Please share these results with the parents of children who attend your center. If you have any questions, please feel free to call me at (303) 312-6579. Thank you for your cooperation in EPA's study.

Sincerely,

Bonnie Lavelle

Remedial Project Manager

attachments

Metals Concentration in Grab Samples Collected at Northeast Montessori Day Care

Parameter	Detection Frequency	Average (ppm)	Max (ppm)	Min (ppm)
Arsenic	12/30	12	19	11
Lead	30/30	200	628	55

**Grab Sample Results** 

Sample ID	Arsenic (ppm)	Lead (ppm)
3-06027-B	11	138
3-06022-B	11	119
3-06023-B	11	152
3-06024-B	11	98
3-06026-B	11	95
3-06028-B	13	151
3-06029-B	12	192
3-06030-B	11	125
3-06321-B	11	104
3-06323 <b>-</b> B	11	263
3-06324-B	12	152
3-06327-B	11	117
3-06328-B	11	122
3-06329-B	13	121
3-06330-B	11	264
3-06322-B	18	300
3-06325-B	12	275
3-06326-B	11	345
3-06332-B	11	195
3-06333-B	13	441
3-06334-В	11	180
3-06335-B	19	254
3-06336-B	11	628
3-06337-B	14	296
3-06340-B	11	136
3-06348-B	11	55
3-06349-B	15	285
3-06350-B	11	166
3-06338-B	11	98
3-06339-B	11	144

MORRISON KNUDSEN CORPORATION			Contract No. 4	_ Contract No. <u>4994</u>		Sheet	
oject	I-70/ Vasquez	Bly &	Designed	4-CA	Date	11-3-99	
	Northeast M	ontisorri Child Care	Checked _	11/1 ·	_ Date	1-3-99	
em							
			•			•	
					N	<b>→</b>	
			•				
					u.		
		=Alley ->		<del></del>	<b>0</b> 1560	= 9	
*			storage & Asi	halt !	(D) 141	1= 1	
9	Planes	Planter		rking	3142	7	
3-01-02		<u> </u>			912	1= 2	
	A COLO	Play-	<b>)</b>		<b>(5)</b> 30	o= 2	
4	3.4.92t R	Ground	1	**************************************	<b>6</b> 50	0:2	
3-06022	RO			1	360	0= <b>2</b>	
	<b>U</b> Y	Ammended ( 9 rass Area	9	3	<b>6</b> 8	0-1	
	3.00.339-R	To Sample Map			@27		
2-1024	L.		•	7	497	15 SQ FT.	
	NO	Longrete	Xe	1			
	क्रियंग्रह	•	Lore de la constitución de la co		<b></b>	an changer.	
306026	9 300 350 8		10	*	30 G	rag samples	
<b>A</b>						- 7	
, A	$\succeq$		en distriction of the control of the	:	W	- 6	
30101	13 (S)	Northcast			1		
	7	child Care Co	nter 1		¥	315 = 10.	
De la Constitución de la Constit	vi B-d34-R	3503 Mario			<b>,</b>	30	
3-06-023	Z.	3503 Mario			1		
			DOT .		¥		
			J.				
0	301347-1		7		Ĭ		
Jum							
12 N 12	K O		- (a)		*		
	J. Suran-Co		306832 R		ŀ	٠.	
				2	*		
1000		6	206305	237-R	¥ .		
3.00	\$ 0L3/0-12 3	6L339FR 200372-1		بيرا	<b>≈</b> ,		
		e- Sidewal	K ->.	ations of the			
131							
12.		The Maddle	1 301328 VI	2000	W.K		
C. 34.0	20	40. 60	80 72	٥		<b>** 1/)</b>	